



**The supplier must manage a quality management system as ISO 9001 type or EN 9100 allowing to satisfy the following clauses :**

1 – The supplier with quality assurance has got the responsibility of doing all the necessary controls in order to check and certify the conformity of the materials with the conditions applicable. The supplier must keep all the records of these control during 10 years except contrary specifications.

2 – The supplier must assure that the tools used for measurement and controls are checked and calibrated. The supplier shall ensure that any calibration laboratory used is recognized for its area of intervention by a national or international approved agency.

3 - If the supplier uses special processes, these processes must be qualified and personnel performing special processes must be authorized by the supplier. This qualification must be followed and recorded. and recorded.

4 - In the case the supplier makes a product under NSE specifications, the product definition must be validated by NSE. Any later evolution of the product must be submitted to NSE for validation.

5 – Since all supplies are qualified (controlled process or BOM), the supplier must advise NSE of any process modification.

6 - The supplier is entirely responsible for the quality of the services ordered, whether it is carried out at his premises or subcontracted. The supplier has to ensure the compliance of his services with the specifications ordered, its annexes, and as considered as state of art.

The supplier must attest to the conformity of his services and be able to prove it throughout product realization and distribution to the representatives of NSE.

The supplier must deliver the equipment with the evidence specified in the order (eg Declaration of conformity, Raw material certificate, Certificate of Airworthiness, Test Report ...).

7 – The supplier should implement suitable means to ensure the traceability of the product from its raw material to final product, throughout product realization and distribution.

The evidence of traceability must be available to NSE representatives.

8 - In case of non-conformity, the supplier must submit a waiver request to NSE Quality Department for approval. Delivery is permitted only after NSE written approval.

9 – Our partners, suppliers and sub-contractors shall record, keep and archive any document issued to ensure quality related to the services that are under their responsibility up to the final conformity documents and this under acceptable conditions for NSE.



10 - The supplier is responsible to ensure the 2nd tier suppliers comply with these clauses and will advise, in writing, NSE of this and abiding these clauses and will advise, in writing, NSE of this 2nd tier sub-contracting.

11 – During audits or tests, the supplier shall ensure that NSE representatives and, where appropriate, representatives of its customers or Official Authorities have free access to facilities and to documentation issued from the services ordered.

	<b>GENERAL QUALITY CONDITIONS</b>	<b>Page 2 / 2</b>
---	-----------------------------------	-------------------

12 – In case of ESD (Electro Static discharge) sensitive equipment. The supplier is responsible for the transport conditions in order to garanty the integrity of the materials.

13 – The supplier must plan, implement and control processes in a manner appropriate to the supplier and the product, to prevent the use of counterfeit or suspected parts and their inclusion in the delivered product (s). ) to NSE.

3	09/02/2018	 <b>D. FOURNES</b>	 <b>LM. BOURCIER</b>
<b>Edition</b>	<b>Date</b>	<b>Direction Achats</b>	<b>Direction Qualité</b>